



# Solar glass cold repair 2025





## Overview

---

Huachuang Securities released a research report saying that there was no cold repair of photovoltaic glass in February, and the overall supply side was stable; After March, the rush to install and the demand resonance in the peak season are expected to significantly improve the.

Huachuang Securities released a research report saying that there was no cold repair of photovoltaic glass in February, and the overall supply side was stable; After March, the rush to install and the demand resonance in the peak season are expected to significantly improve the.

As of July, the designed capacity under cold repair for photovoltaic (PV) glass has reached 3,600 tons/day, while the actual production cut capacity has exceeded 4,000 tons/day. Currently, total cold repair capacity accounts for 29.47% of the domestic PV glass production capacity. Including sealed.

(Yicai) Sept. 5 -- Major Chinese producers of photovoltaic glass confirmed that they are idling furnaces to reduce output in response to a severe supply glut, but industry insiders are unsure whether this will be enough to restore the balance to supply and demand. Listed solar glass manufacturers.

[SMM Silicon-Based PV Morning Meeting Summary: Sudden Increase in Glass Cold Repair Scale, Module Inventory Pressure Eased] In January, a total of 2,800 mt/day of furnace water cooling repairs were conducted domestically, in addition to 1,650 mt/day of furnace shutdowns for kiln maintenance. The.

Market sources indicate that multiple production lines in China's glass industry underwent shutdowns and maintenance in November. At the beginning of the month, four production lines in the Shahe region halted operations to advance the "coal-to-gas" conversion project. By month-end, several lines.

Company Glass Technology is an experienced and trusted player in the global glass manufacturing industry who is specialized in the production of low-iron solar glass. The German engineering company HORN is a reliable partner in the flat glass industry and has comprehensive knowledge from the first.

PVTIME – On 23 November 2023, Zhuzhou Kibing Group Co., Ltd. (Kibing Glass)



(601636.SH), one of the largest glass producers in China, announced its intention to repair the float glass furnace at three production lines in 2024 as part of their upgrade plan. The schedule for cold repairs and.



## Solar glass cold repair 2025



### [\[SMM Analysis: Rapid Improvement in Glass Market, Planned ...\]](#)

With the rapid recovery of demand, the supply shortage of glass in H1 is expected to become evident, strengthening the upward price trend. Some planned cold repairs of ...

### [Horn News spring/summer 2025 \(status: March 24, 2025\)](#)

In the second half of 2025, the solar glass line will already be operational. The new production facility will create about 150 new jobs in Al Ghail Industrial Zone, UAE.



### **[SMM Analysis: Rapid Improvement in Glass Market, Planned Cold Repair]**

With the rapid recovery of demand, the supply shortage of glass in H1 is expected to become evident, strengthening the upward price trend. Some planned cold repairs of ...



### **Glass Cold Repair Scale Surges, Module Inventory Pressure ...**

The supply decreased significantly, and more furnaces are expected to undergo cold repairs in the future.



### [Understanding and preventing PV module glass fracture](#)

In a feature article for PV Tech Power (Q3 2025), David Devir, principal engineer for VDE Americas, looks at the origins of today's supersized PV module glass problem and ...

### **Huachuang Securities: The price of new orders for photovoltaic ...**

In February, there was no cold repair of photovoltaic glass, and the overall supply side was stable. According to Zhuochuang information, since 2025, only 3,700t/d photovoltaic ...



### **Optimising glass furnace operations**

The aim of this article is to give an overview of possibilities offered for hot and cold repairs, illustrated with two real-case scenarios ...



### **SunSirs: Glass: Cold Repairs and Production Cuts Take Effect, ...**



With production lines undergoing cold repairs and overall industry capacity utilization declining, the market is nearing supply-demand equilibrium, and inventory is ...



### **PV Glass Cold Repair Capacity Expands Further in July! Weaker ...**

The production cut on the supply side is progressing at a decent pace, and additional cold repair plans remain in place. For the remainder of July, another 1,400 tons/day ...



### **Huachuang Securities: The price of new orders for photovoltaic glass ...**

In February, there was no cold repair of photovoltaic glass, and the overall supply side was stable. According to Zhuochuang information, since 2025, only 3,700t/d photovoltaic ...



### **[Big Chinese Solar Glass Makers Confirm Output Cuts Amid ...](#)**

Listed solar glass manufacturers have been putting furnaces into 'cold repair' status since the start of the second half, sources told Yicai. Facilities that would normally produce ...



### **Kibin Glass to Upgrade PV Glass Furnace Via Cold Repair in 2024**



The schedule for cold repairs and resumption of production has not yet been disclosed. The decision to conduct maintenance on the production line will depend on the time ...



### [Kibin Glass to Upgrade PV Glass Furnace Via ...](#)

The schedule for cold repairs and resumption of production has not yet been disclosed. The decision to conduct maintenance on the ...



### **Optimising glass furnace operations**

The aim of this article is to give an overview of possibilities offered for hot and cold repairs, illustrated with two real-case scenarios with outcomes from the repair work done on ...





## Contact Us

---

For catalog requests, pricing, or partnerships, please visit:

<https://asimer.es>

Phone: +34 910 56 87 42

Email: [info@asimer.es](mailto:info@asimer.es)

Scan the QR code to access our WhatsApp.

